Oil Field Environmental Incident Summary

Responsible Party: STATOIL OIL & GAS LP **Well Operator:** STATOIL OIL & GAS LP

Well Name: CHERYL 17-20 2TFH

Field Name: BANKS Well File #: 22322

Date Incident:7/16/2014Time Incident:12:00Facility ID Number:County:MCKENZIETwp:152Rng:98Sec:8Qtr:

Location Description: Area of displacement off site was approximately 150' X 200' to the east of the

flare pit.

Submitted By: Jeremy Mohl Received By:

Contact Person: Jeremy Mohl

6300 BRIDGE POINT PKY, BLDG 2

SUITE 500

AUSTIN, TX 78730

General Land Use: Well/Facility Site Affected Medium: Topsoil

Distance Nearest Occupied Building:1 MileDistance Nearest Water Well:1 Mile

Type of Incident: Vessel Leak

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units
Oil 1 Barrels 1 Barrels 1 barrels

Brine Other

Description of Other Released Contaminant:

None

Inspected: Written Report Received: 9/1/2016 Clean Up Concluded: 7/31/2014

Risk Evaluation:No immediate risk.

Areal Extent:

Area of displacement off site was approximately 150' X 200' to the east of the flare pit.

Potential Environmental Impacts:

None

Action Taken or Planned:

P&J was contacted for removal and replacement of impacted materials. Site has been remediated.

Wastes Disposal Location: All solids and semi-solids were disposed at PDI Disposal.

Agencies Involved:

Updates

Date: 7/17/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from a vessel leak sprayed off location. Followup is necessary.

Date: 7/31/2014 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 15:45 7/31/14.

Incident happened at the same location as the Richard 8-5 #2H. See the Richard 8-5 #2H incident summary.

No follow up necessary.